
STATUTORY INSTRUMENTS

1956 No. 1942

The Coal Mines (Cardox and Hydrox) Regulations 1956

PART II

Miss-fires

- 26.** If any shell fails to fire, the person attempting to fire the shell—
- (a) shall not himself approach nor allow any other person to approach the shell during the interval of ten minutes after such attempt;
 - (b) before approaching or allowing any other person to approach the shell shall disconnect the removable handle or key and the cable from the shot firing apparatus;
 - (c) shall then examine the cable and connections for any defect;
 - (d) if he leaves the working place while the shell remains there shall cause notice of the miss-fire to be given to the deputy in charge of the district and ensure that sufficient fences and danger notices are erected to notify the miss-fire to any person approaching the place.
- 27.** If any shell fails to fire, no person shall attempt to remove it from its hole until any external firing wire has been disconnected from it.