
STATUTORY INSTRUMENTS

2006 No. 2739

The Control of Asbestos Regulations 2006

PART 2

GENERAL REQUIREMENTS

Cleanliness of premises and plant

17. Every employer who undertakes work which exposes or is liable to expose his employees to asbestos shall ensure that—

- (a) the premises, or those parts of the premises where that work is carried out, and the plant used in connection with that work are kept in a clean state; and
- (b) where such work has been completed, the premises, or those parts of the premises where the work was carried out, are thoroughly cleaned.